

D

Е

CONTENTS

PRECAUTION2
PRECAUTIONS2
FOR USA AND CANADA
FOR MEXICO
PREPARATION5
PREPARATION
SYSTEM DESCRIPTION6
DOOR MIRROR SYSTEM
INSIDE MIRROR SYSTEM
DTC/CIRCUIT DIAGNOSIS8
DOOR MIRROR REMOTE CONTROL SWITCH (MIRROR SWITCH/CHANGEOVER SWITCH)8 Component Inspection8

DOOR MIRROR	F
AUTO ANTI-DAZZLING INSIDE MIRROR SYSTEM12 Wiring Diagram12	(
SYMPTOM DIAGNOSIS14	ŀ
SQUEAK AND RATTLE TROUBLE DIAG- NOSES14 Work Flow14	
Inspection Procedure	
REMOVAL AND INSTALLATION20	
INSIDE MIRROR20Exploded View20Removal and Installation20	ŀ
OUTSIDE MIRROR21	M
DOOR MIRROR ASSEMBLY21 DOOR MIRROR ASSEMBLY : Exploded View21 DOOR MIRROR ASSEMBLY : Removal and Installation	N
GLASS MIRROR	1
DOOR MIRROR COVER	F
DOOR MIRROR REMOTE CONTROL SWITCH	

PRECAUTION

PRECAUTIONS FOR USA AND CANADA

FOR USA AND CANADA: Precaution for Supplemental Restraint System (SRS) "AIR BAG" and "SEAT BELT PRE-TENSIONER"

The Supplemental Restraint System such as "AIR BAG" and "SEAT BELT PRE-TENSIONER", used along with a front seat belt, helps to reduce the risk or severity of injury to the driver and front passenger for certain types of collision. This system includes seat belt switch inputs and dual stage front air bag modules. The SRS system uses the seat belt switches to determine the front air bag deployment, and may only deploy one front air bag, depending on the severity of a collision and whether the front occupants are belted or unbelted. Information necessary to service the system safely is included in the "SRS AIR BAG" and "SEAT BELT" of this Service Manual.

WARNING:

- To avoid rendering the SRS inoperative, which could increase the risk of personal injury or death in the event of a collision which would result in air bag inflation, all maintenance must be performed by an authorized NISSAN/INFINITI dealer.
- Improper maintenance, including incorrect removal and installation of the SRS, can lead to personal injury caused by unintentional activation of the system. For removal of Spiral Cable and Air Bag Module, see the "SRS AIR BAG".
- Do not use electrical test equipment on any circuit related to the SRS unless instructed to in this Service Manual. SRS wiring harnesses can be identified by yellow and/or orange harnesses or harness connectors.

PRECAUTIONS WHEN USING POWER TOOLS (AIR OR ELECTRIC) AND HAMMERS

WARNING:

- When working near the Air Bag Diagnosis Sensor Unit or other Air Bag System sensors with the ignition ON or engine running, DO NOT use air or electric power tools or strike near the sensor(s) with a hammer. Heavy vibration could activate the sensor(s) and deploy the air bag(s), possibly causing serious injury.
- When using air or electric power tools or hammers, always switch the ignition OFF, disconnect the battery, and wait at least 3 minutes before performing any service.

FOR USA AND CANADA: Precaution Necessary for Steering Wheel Rotation after Battery Disconnect

NOTE:

- Before removing and installing any control units, first turn the push-button ignition switch to the LOCK position, then disconnect both battery cables.
- After finishing work, confirm that all control unit connectors are connected properly, then re-connect both battery cables.
- Always use CONSULT-III to perform self-diagnosis as a part of each function inspection after finishing work.
 If a DTC is detected, perform trouble diagnosis according to self-diagnosis results.

For vehicle with steering lock unit, if the battery is disconnected or discharged, the steering wheel will lock and cannot be turned.

If turning the steering wheel is required with the battery disconnected or discharged, follow the operation procedure below before starting the repair operation.

OPERATION PROCEDURE

Connect both battery cables.

NOTE:

Supply power using jumper cables if battery is discharged.

- 2. Turn the push-button ignition switch to ACC position. (At this time, the steering lock will be released.)
- Disconnect both battery cables. The steering lock will remain released with both battery cables disconnected and the steering wheel can be turned.
- 4. Perform the necessary repair operation.

PRECAUTIONS

< PRECAUTION >

- 5. When the repair work is completed, re-connect both battery cables. With the brake pedal released, turn the push-button ignition switch from ACC position to ON position, then to LOCK position. (The steering wheel will lock when the push-button ignition switch is turned to LOCK position.)
- Perform self-diagnosis check of all control units using CONSULT-III.

FOR USA AND CANADA: Precaution for Battery Service

Before disconnecting the battery, lower both the driver and passenger windows. This will prevent any interference between the window edge and the vehicle when the door is opened/closed. During normal operation, the window slightly raises and lowers automatically to prevent any window to vehicle interference. The automatic window function will not work with the battery disconnected.

FOR MEXICO

FOR MEXICO: Precaution for Supplemental Restraint System (SRS) "AIR BAG" and "SEAT BELT PRE-TENSIONER"

The Supplemental Restraint System such as "AIR BAG" and "SEAT BELT PRE-TENSIONER", used along with a front seat belt, helps to reduce the risk or severity of injury to the driver and front passenger for certain types of collision. Information necessary to service the system safely is included in the "SRS AIR BAG" and "SEAT BELT" of this Service Manual.

WARNING:

- To avoid rendering the SRS inoperative, which could increase the risk of personal injury or death in the event of a collision which would result in air bag inflation, all maintenance must be performed by an authorized NISSAN/INFINITI dealer.
- Improper maintenance, including incorrect removal and installation of the SRS, can lead to personal
 injury caused by unintentional activation of the system. For removal of Spiral Cable and Air Bag
 Module, see the "SRS AIR BAG".
- Do not use electrical test equipment on any circuit related to the SRS unless instructed to in this Service Manual. SRS wiring harnesses can be identified by yellow and/or orange harnesses or harness connectors.

PRECAUTIONS WHEN USING POWER TOOLS (AIR OR ELECTRIC) AND HAMMERS

WARNING.

- When working near the Air Bag Diagnosis Sensor Unit or other Air Bag System sensors with the
 ignition ON or engine running, DO NOT use air or electric power tools or strike near the sensor(s)
 with a hammer. Heavy vibration could activate the sensor(s) and deploy the air bag(s), possibly
 causing serious injury.
- When using air or electric power tools or hammers, always switch the ignition OFF, disconnect the battery, and wait at least 3 minutes before performing any service.

FOR MEXICO: Precaution Necessary for Steering Wheel Rotation after Battery Disconnect

NOTE:

- Before removing and installing any control units, first turn the push-button ignition switch to the LOCK position, then disconnect both battery cables.
- After finishing work, confirm that all control unit connectors are connected properly, then re-connect both battery cables.
- Always use CONSULT-III to perform self-diagnosis as a part of each function inspection after finishing work.
 If a DTC is detected, perform trouble diagnosis according to self-diagnosis results.

For vehicle with steering lock unit, if the battery is disconnected or discharged, the steering wheel will lock and cannot be turned.

If turning the steering wheel is required with the battery disconnected or discharged, follow the operation procedure below before starting the repair operation.

OPERATION PROCEDURE

Connect both battery cables.

NOTE:

- Supply power using jumper cables if battery is discharged.
- 2. Turn the push-button ignition switch to ACC position.

MIR

J

В

D

INFOID:0000000005234698

M

Ν

0

0- P

Revision: 2009 July MIR-3 2010 370Z

PRECAUTIONS

< PRECAUTION >

(At this time, the steering lock will be released.)

- Disconnect both battery cables. The steering lock will remain released with both battery cables disconnected and the steering wheel can be turned.
- 4. Perform the necessary repair operation.
- 5. When the repair work is completed, re-connect both battery cables. With the brake pedal released, turn the push-button ignition switch from ACC position to ON position, then to LOCK position. (The steering wheel will lock when the push-button ignition switch is turned to LOCK position.)
- 6. Perform self-diagnosis check of all control units using CONSULT-III.

FOR MEXICO: Precaution for Battery Service

INFOID:0000000005532121

Before disconnecting the battery, lower both the driver and passenger windows. This will prevent any interference between the window edge and the vehicle when the door is opened/closed. During normal operation, the window slightly raises and lowers automatically to prevent any window to vehicle interference. The automatic window function will not work with the battery disconnected.

PREPARATION

< PREPARATION >

PREPARATION

PREPARATION

Commercial Service Tools

	Tool name	Description
Remover tool	JMKIA3050ZZ	Removes the clips, pawls and metal clips

С

D

В

INFOID:0000000005234699

Α

Е

F

G

Н

J

Κ

MIR

M

Ν

0

Р

DOOR MIRROR SYSTEM

< SYSTEM DESCRIPTION >

SYSTEM DESCRIPTION

DOOR MIRROR SYSTEM

Component Description

INFOID:0000000005234688

Component	Function
Door mirror remote control switch	It supplies power to mirror motor through mirror switch and changeover switch.
Door mirror	It makes mirror face operate from side to side and up and down with the mirror control switch operation.

INSIDE MIRROR SYSTEM

< SYSTEM DESCRIPTION >

INSIDE MIRROR SYSTEM

System Description

INFOID:0000000005234689

The sensor built in inside mirror detects the headlight of the vehicle behind and automatically changes the light transmission to decrease the brightness.

Component Description

INFOID:0000000005234690

Component	Function
Auto anti-dazzling inside mirror	It automatically changes the light transmittance according to the brightness of the light from the headlight of the vehicle behind.

Е

D

Α

F

G

Н

J

K

MIR

M

Ν

0

Р

DOOR MIRROR REMOTE CONTROL SWITCH (MIRROR SWITCH/ CHANGEOVER SWITCH)

< DTC/CIRCUIT DIAGNOSIS >

DTC/CIRCUIT DIAGNOSIS

DOOR MIRROR REMOTE CONTROL SWITCH (MIRROR SWITCH/ CHANGEOVER SWITCH)

Component Inspection

INFOID:0000000005550874

1. CHECK MIRROR SWITCH & CHANGEOVER SWITCH

- 1. Turn ignition switch OFF.
- 2. Disconnect door mirror remote control switch connector.
- Check door mirror remote control switch.

[Door mirror (driver side)]

Door mirror	remote control switch		Mirror switch condition	Continuity			
Connector	Tern	ninal	Will of Switch Condition	Continuity			
	7	7 10 RIGHT	DICUT				
	1	14	RIGHT				
	7	14	LEFT	Existed			
D7	1	10	LEFI				
D1	7	16	UP				
	1	10	UP				
	7	10	DOWN				
	1	16	DOWN				

[Door mirror (passenger side)]

Door mirror	r remote control swit	ch	Mirror switch condition	Continuity		
Connector						
	7 12 RIGHT					
	1	13	RIGHT			
	7	13	LEFT			
D7	1	12	LEFI	Evictod		
D1	7	15	UP	Existed		
	1	12	UP			
	7	12	12 DOWN			
	1	15	DOWN			

Is the inspection result normal?

YES >> INSPECTION END.

NO >> Replace door mirror remote control switch.Refer to MIR-25, "Removal and Installation".

Revision: 2009 July MIR-8 2010 370Z

DOOR MIRROR

Wiring Diagram

Α

В

JCLWA2600GB

C DOOR MIRROR (PASSENGER SIDE) DOOR MIRROR (DRIVER SIDE) D RIGHTWARD

LEFTWARD

H UPWARD

DOWNWARD RIGHTWARD

LEFTWARD

LEFTWARD

A UPWARD

DOWNWARD Е F (031) M124 (0)53 G 53 53 53 53 Н J Κ DOOR MIRROR REMOTE
CONTROL SWITCH
(D7) MIR MIRROR SWITCH \mathbb{N} FUSE BLOCK (J/B) (M1) Ν 52 D1 13 O1 0 2008/09/12 Ρ

DOOR MIRROR

	8 8		ſ		7A 6A 5A			o _N	1A	ם פ		5A L	V 46 × 10 × 10 × 10 × 10 × 10 × 10 × 10 × 1	/A DK			- [Coupe models]	- [Roadster models]					SENGER SIDE)				Γ			7		Signal Name [Specification]	- [Coupe models]	
Connection No.	1	T	Connector Type TH40FW-CS15	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	Terminal Color Signal Name No. of Wire	Н	11 LG - [With BO	ΓG	> -	13 L - Lexcept for coupe mod	15 W	а.			- >	52 G	BG	53 O - [Roadst	╀		ſ	Connector No. D33	Connector Name DOOR MIRROR (PASSENGER SIDE)	Connector Type TH08MW-NH		MATI		1 2 3 4	Ì		- 1	Terminal Color Signal Name	BG	
	D3	DOOR MIRROR (DRIVER SIDE)	TH08MW-NH	1	Signal Name [Specification]	1	1 1	_	-		D7	DOOR MIRROR REMOTE CONTROL SWITCH	т	INIOPW			1	8 9 10 12 13 14 15 16			Signal Name [Specification]			1	1	1	'		slehom emion) =		-			
Manage	Connector No.	Connector Name	Connector Type	H.S.	Terminal Color No. of Wire	1 BR	3 2	4	8 8		Connector No.	Connector Name	F	edi laberon labe	(F	SE			J		-ea	No. of Wire		. 8	9	+	+	13 EE	15 BG	12	Н			
ROR	UI	WIRE TO WIRE	TH40FW-CS15		Signal Name [Specification]	1	1 1	- [Coupe models]	- [Roadster models]	- [With BOSE system] - [Without BOSE system]	1	1	- [Coupe models]	- [Koadster models]	1	-	1			_	-		- [Coupe models]	Fernancia (asengo)	-									
DOOR MIRROR	-		Connector Type		nal Color of Wire	> :	> Ø	H	0	+	٦	Н	gg >	+	╀	Н	\dashv	В	+	+	+	+	. R	╀	Н									
ջ	oune	onne	Sonne	图 HS.	Terminal No.	-		10	2	= =	12	13	4 :	± 5	61	23	44	47	9	20	21	25	2 2	\$ 25	22									

JCLWM4045GB

- [Coupe models]	- [Roadster models]	- [Coupe models]	- [Roadster models]	1	+	-	=	1	-	- [Coupe models]	- [Roadster models]	=	=	[Roadster models with M/T]	 [Except for roadster models with M/T] 	-	-	1
G	۸	۸	57	57	۸	В	W	Υ	Y/B	В	0	Υ	Υ	G	GR	W	G	œ
10	01	1.1	1.1	12	13	14	91	19	23	44	44	90	19	25	25	23	54	99

DOOR MIRROR
Connector No. M5

Ferminal Color			
Signal Name (Specification)	Connecto		TH40MW-CS15
	匮		•
Signal Name (Specification)	HS	1 2 3	7 8 9 10 11 12 13 14 12 13 14 14 15 15 14 15 15 14 15 15
Signal Name [Specification]			
	Terminal No.	Color of Wire	Name
	7	>	ı
	8	Υ	-
	6	G	-
	10	^	1
C	Ξ	^	1
	12	٦	ı
C	13	В	1
	14	Υ	1
	15	W	1
	19	Υ	1
	23	Y/B	1
-	44	L	1
- [Roadster models with M/T]	47	В	1
- [Roadster models with M.T]	48	SB	1
	49	SB	- [Roadster models with M/T]
M124 M124 TH40MW-CS15 T S S T S S T S S T S S	46	Υ	 [Except for roadster models with M/T]
M124 MIETO WIFE TO WIFE TH40MW-CS15	20	W	-
M124 M124	51	В	ı
M124 WIRE TO WIRE TH40MW-CS15 S S S S S S	52	٦	1
M124 WIRE TO WIRE TH40MW-CS15 TH40MW-CS16 S 3 4 5 6 7 8	53	M	1
M124 WIRE TO WIRE TH40MW-CS15	54	9	-
MI24 WIRE TO WIRE TH40MW-CS15 3 4 5 6 7 8 18 18 18 18 18 18	99	В	-
M124 WIRE TO WIRE TH40MW-CS15 TH40MW-CS15			
WIRE TO WIRE TH40MW-CS15	Connecto	r No.	M124
TH40MW-CS15	Connector	r Name	2
	Connector	r Type	TH40MW-CS15
S	E C		
	H.S.	0	7 8 7
		16171819	-1

Terminal Color Signal Name [Specification]

JCLWM4046GB

Α

В

С

 D

Е

F

G

Н

1

J

Κ

MIR

M

Ν


0

Р

AUTO ANTI-DAZZLING INSIDE MIRROR SYSTEM

Wiring Diagram





INSIDE MIRROR

JCLWM4047GB 2009/07/10

AUTO ANTI-DAZZLING INSIDE MIRROR SYSTEM

< DTC/CIRCUIT DIAGNOSIS >


		А
WIRE NH NH NH Signal Name [Specification]		В
111 M WR TO 111 11 11 11 11 11 11 11 11 11 11 11 1		С
Connector No. Connector Name Connector Name Connector Type No.		D
ilfred from infration infr		Е
Re		F
N N N N N N N N N N		G
16 16 17 17 17 17 17 17		Н
WIRE NH Signal Name [Specification] Signal Name [Specification]		I
WRE TO WRE TO 1188 HISAW.		J
Connector No. A A	_	K
		MIR
OCK (J/B) M2 M2 M2 M3 CCK (J/B) CCK (J		M
HRROA NISOGFW NISOGFW NISOGFW NISOGFW NISOGFW NISOGFW NISOGFW NISOFFW		Ν
INSIDE MIRROR Connector No. MI Connector No. Connector No. Connector Type NSIOFW- Connector Type NSIOFW- Connector No. Con		0
	JCLWM4048GB	Р

Revision: 2009 July MIR-13 2010 370Z

SYMPTOM DIAGNOSIS

SQUEAK AND RATTLE TROUBLE DIAGNOSES

Work Flow



CUSTOMER INTERVIEW

Interview the customer if possible, to determine the conditions that exist when the noise occurs. Use the Diagnostic Worksheet during the interview to document the facts and conditions when the noise occurs and any of customer's comments; refer to MIR-18, "Diagnostic Worksheet". This information is necessary to duplicate the conditions that exist when the noise occurs.

- The customer may not be able to provide a detailed description or the location of the noise. Attempt to obtain all the facts and conditions that exist when the noise occurs (or does not occur).
- If there is more than one noise in the vehicle, perform a diagnosis and repair the noise that the customer is concerned about. This can be accomplished by performing a cruise test on the vehicle with the customer.
- After identifying the type of noise, isolate the noise in terms of its characteristics. The noise characteristics
 are provided so the customer, service adviser and technician are all speaking the same language when
 defining the noise.
- Squeak (Like tennis shoes on a clean floor)
 Squeak characteristics include the light contact/fast movement/brought on by road conditions/hard surfaces
 higher pitch noise/softer surfaces = lower pitch noises/edge to surface = chirping
- Creak (Like walking on an old wooden floor)
 Creak characteristics include firm contact/slow movement/twisting with a rotational movement/pitch dependent on materials/often brought on by activity.
- Rattle (Like shaking a baby rattle)
 Rattle characteristics include the fast repeated contact/vibration or similar movement/loose parts/missing clip or fastener/incorrect clearance.
- Knock (Like a knock on a door)

 Knock share stariation include halls
 - Knock characteristics include hollow sounding/sometimes repeating/often brought on by driver action.
- Tick (Like a clock second hand)
 Tick characteristics include gentle contacting of light materials/loose components/can be caused by driver action or road conditions.
- Thump (Heavy, muffled knock noise)
 Thump characteristics include softer knock/dead sound often brought on by activity.
- Buzz (Like a bumblebee)
 Buzz characteristics include high frequency rattle/firm contact.
- Often the degree of acceptable noise level will vary depending up on the person. A noise that a technician may judge as acceptable may be very irritating to the customer.
- Weather conditions, especially humidity and temperature, may have a great effect on noise level.

DUPLICATE THE NOISE AND TEST DRIVE

< SYMPTOM DIAGNOSIS >

If possible, drive the vehicle with the customer until the noise is duplicated. Note any additional information on the Diagnostic Worksheet regarding the conditions or location of the noise. This information can be used to duplicate the same conditions when the repair is reconfirmed.

If the noise can be duplicated easily during the test drive, to help identify the source of the noise, try to duplicate the noise with the vehicle stopped by doing one or all of the following:

- 1) Close a door.
- 2) Tap or push/pull around the area where the noise appears to be coming from.
- 3) Rev the engine.
- 4) Use a floor jack to recreate vehicle "twist".
- 5) At idle, apply engine load (electrical load, half-clutch on M/T models, drive position on A/T models).
- 6) Raise the vehicle on a hoist and hit a tire with a rubber hammer.
- Drive the vehicle and attempt to duplicate the conditions the customer states exist when the noise occurs.
- If it is difficult to duplicate the noise, drive the vehicle slowly on an undulating or rough road to stress the vehicle body.

CHECK RELATED SERVICE BULLETINS

After verifying the customer concern or symptom, check ASIST for Technical Service Bulletins (TSBs) related to that concern or symptom.

If a TSB relates to the symptom, follow the procedure to repair the noise.

LOCATE THE NOISE AND IDENTIFY THE ROOT CAUSE

- 1. Narrow down the noise to a general area. To help pinpoint the source of the noise, use a listening tool (Chassis ear: J-39570, Engine ear and mechanics stethoscope).
- 2. Narrow down the noise to a more specific area and identify the cause of the noise by:
- Removing the components in the area that is are suspected to be the cause of the noise.
 Do not use too much force when removing clips and fasteners, otherwise clips and fastener can be broken

or lost during the repair, resulting in the creation of new noise.

Tapping or pushing/pulling the component that is are suspected to be the cause of the noise.

- Tapping or pushing/pulling the component that is are suspected to be the cause of the noise.
 Do not tap or push/pull the component with excessive force, otherwise the noise will be eliminated only temporarily.
- Feeling for a vibration by hand by touching the component(s) that is are suspected to be the cause of the noise.
- Placing a piece of paper between components that are suspected to be the cause of the noise.
- Looking for loose components and contact marks.
 Refer to MIR-16, "Inspection Procedure".

REPAIR THE CAUSE

- If the cause is a loose component, tighten the component securely.
- If the cause is insufficient clearance between components:
- Separate components by repositioning or loosening and retightening the component, if possible.
- Insulate components with a suitable insulator such as urethane pads, foam blocks, felt cloth tape or urethane tape. A Nissan Squeak and Rattle Kit (J-43980) is available through the authorized Nissan Parts Department.

CAUTION:

Never use excessive force as many components are constructed of plastic and may be damaged. NOTE:

Always check with the Parts Department for the latest parts information.

The following materials are contained in the Nissan Squeak and Rattle Kit (J-43980). Each item can be ordered separately as needed.

MIR-15

URETHANE PADS [1.5 mm (0.059 in) thick]

Insulates connectors, harness, etc.

76268-9E005: 100 \times 135 mm (3.94 \times 5.31 in)/76884-71L01: 60 \times 85 mm (2.36 \times 3.35 in)/76884-

71L02:15 \times 25 mm (0.59 \times 0.98 in)

INSULATOR (Foam blocks)

Insulates components from contact. Can be used to fill space behind a panel.

73982-9E000: 45 mm (1.77 in) thick, 50×50 mm (1.97 \times 1.97 in)/73982-

50Y00: 10 mm (0.39 in) thick, 50 \times 50 mm (1.97 \times 1.97 in)

INSULATOR (Light foam block)

80845-71L00: 30 mm (1.18 in) thick, 30 \times 50 mm (1.18 \times 1.97in)

FELT CLOTHTAPE

Used to insulate where movement does not occur. Ideal for instrument panel applications.

MIR

J

K

В

D

Е

F

....

. .

 \mathbb{N}

N

O

Ρ

< SYMPTOM DIAGNOSIS >

68370-4B000: 15 \times 25 mm (0.59 \times 0.98 in) pad/68239-13E00: 5 mm (0.20 in) wide tape roll

The following materials, not found in the kit, can also be used to repair squeaks and rattles.

UHMW (TEFLON) TAPE

Insulates where slight movement is present. Ideal for instrument panel applications.

SILICONE GREASE

Used in place of UHMW tape that is be visible or does not fit. Will only last a few months.

SILICONE SPRAY

Used when grease cannot be applied.

DUCT TAPE

Used to eliminate movement.

CONFIRM THE REPAIR

Confirm that the cause of a noise is repaired by test driving the vehicle. Operate the vehicle under the same conditions as when the noise originally occurred. Refer to the notes on the Diagnostic Worksheet.

Inspection Procedure

NEOID:000000000523469

Refer to Table of Contents for specific component removal and installation information.

INSTRUMENT PANEL

Most incidents are caused by contact and movement between:

- 1. The cluster lid A and instrument panel
- 2. Acrylic lens and combination meter housing
- Instrument panel to front pillar garnish
- 4. Instrument panel to windshield
- 5. Instrument panel mounting pins
- 6. Wiring harnesses behind the combination meter
- 7. A/C defroster duct and duct joint

These incidents can usually be located by tapping or moving the components to duplicate the noise or by pressing on the components while driving to stop the noise. Most of these incidents can be repaired by applying felt cloth tape or silicon spray (in hard to reach areas). Urethane pads can be used to insulate wiring harness.

CAUTION:

Never use silicone spray to isolate a squeak or rattle. If the area is saturated with silicone, the recheck of repair becomes impossible.

CENTER CONSOLE

Components to pay attention to include:

- Shifter assembly cover to finisher
- 2. A/C control unit and cluster lid C
- 3. Wiring harnesses behind audio and A/C control unit

The instrument panel repair and isolation procedures also apply to the center console.

DOORS

Pay attention to the following:

- Finisher and inner panel making a slapping noise
- 2. Inside handle escutcheon to door finisher
- Wiring harnesses tapping
- 4. Door striker out of alignment causing a popping noise on starts and stops

Tapping or moving the components or pressing on them while driving to duplicate the conditions can isolate many of these incidents. The areas can usually be insulated with felt cloth tape or insulator foam blocks from the Nissan Squeak and Rattle Kit (J-43980) to repair the noise.

TRUNK

Trunk noises are often caused by a loose jack or loose items put into the trunk by the customer. In addition look for the following:

- Trunk lid dumpers out of adjustment
- 2. Trunk lid striker out of adjustment

Revision: 2009 July MIR-16 2010 370Z

< SYMPTOM DIAGNOSIS >

- The trunk lid torsion bars knocking together
- A loose license plate or bracket

Most of these incidents can be repaired by adjusting, securing or insulating the item(s) or component(s) causing the noise.

SUNROOF/HEADLINING

Noises in the sunroof/headlining area can often be traced to one of the following:

- Sunroof lid, rail, linkage or seals making a rattle or light knocking noise
- Sunvisor shaft shaking in the holder
- 3. Front or rear windshield touching headlining and squeaking

Again, pressing on the components to stop the noise while duplicating the conditions can isolate most of these incidents. Repairs usually consist of insulating with felt cloth tape.

SEATS

When isolating seat noise it's important to note the position the seats in and the load placed on the seat when the noise occurs. These conditions should be duplicated when verifying and isolating the cause of the noise. Cause of seat noise include:

- Headrest rods and holder
- A squeak between the seat pad cushion and frame
- The rear seatback lock and bracket

These noises can be isolated by moving or pressing on the suspected components while duplicating the conditions under which the noise occurs. Most of these incidents can be repaired by repositioning the component or applying urethane tape to the contact area.

UNDERHOOD

Some interior noise may be caused by components under the hood or on the engine wall. The noise is then transmitted into the passenger compartment.

Causes of transmitted underhood noise include:

- 1. Any component mounted to the engine wall
- 2. Components that pass through the engine wall
- Engine wall mounts and connectors 3.
- Loose radiator mounting pins
- Hood bumpers out of adjustment
- Hood striker out of adjustment

These noises can be difficult to isolate since they cannot be reached from the interior of the vehicle. The best method is to secure, move or insulate one component at a time and test drive the vehicle. Also, engine RPM or load can be changed to isolate the noise. Repairs can usually be made by moving, adjusting, securing, or insulating the component causing the noise.

MIR

M

N

Р

MIR-17 Revision: 2009 July 2010 370Z

K

Α

В

D

Е

F

Н

Diagnostic Worksheet

INFOID:0000000005234695




SQUEAK & RATTLE DIAGNOSTIC WORKSHEET

Dear Nissan Customer:

We are concerned about your satisfaction with your Nissan vehicle. Repairing a squeak or rattle sometimes can be very difficult. To help us fix your Nissan right the first time, please take a moment to note the area of the vehicle where the squeak or rattle occurs and under what conditions. You may be asked to take a test drive with a service advisor or technician to ensure we confirm the noise you are hearing.

I. WHERE DOES THE NOISE COME FROM? (circle the area of the vehicle)

The illustrations are for reference only, and may not reflect the actual configuration of your vehicle.



Continue to page 2 of the worksheet and briefly describe the location of the noise or rattle. In addition, please indicate the conditions which are present when the noise occurs.

PIIB8740E

< SYMPTOM DIAGNOSIS >


SQUEAK & RATTLE DIAGNOSTIC WO Briefly describe the location where the n					
II. WHEN DOES IT OCCUR? (please ch	neck the box	ces that ap	ply)		
anytime	☐ after	r sitting ou	ıt in the ra	in	
1st time in the morning		n it is rain	_	t	
only when it is cold outside		or dusty co	onditions		
only when it is hot outside	☐ othe	r:			
III. WHEN DRIVING:	IV. WH	AT TYPE	OF NOIS	E	
through driveways	☐ sque	eak (like te	ennis sho	es on a clean floor)	
over rough roads			_	n old wooden floor)	
over speed bumps		e (like sha	_		
only about mph		ck (like a k		,	
on acceleration		(like a clo		•	
☐ coming to a stop☐ on turns: left, right or either (circle)		np (neavy z (like a bı		knock noise)	
with passengers or cargo		د (iike a bi	amble bee	₹)	
ther:	_				
after driving miles or m	inutes				
TO BE COMPLETED BY DEALERSHII	PERSONI	NEL			
Test Drive Notes:					
					_
		YES	NO	Initials of person performing	N
Vehicle test driven with customer					
 Noise verified on test drive 					
Noise verified on test driveNoise source located and repaired					
	rm repair				
Noise source located and repairedFollow up test drive performed to confi	•	□ □ tomer Nar	 ne:		
- Noise source located and repaired	Cus	□ □ stomer Nar			
 Noise source located and repaired Follow up test drive performed to confi VIN: 	Cus	e: ——			
- Noise source located and repaired - Follow up test drive performed to confi VIN:	Cus	e: ——			

Revision: 2009 July MIR-19 2010 370Z

REMOVAL AND INSTALLATION

INSIDE MIRROR

Exploded View



- 1. Windshield glass
- 2. Mirror base
- 4. TORX bolt
- 5. Inside mirror
- Refer to GI-4, "Components" for symbols in the figure.

- 3. Harness connector
- Inside mirror cover

Removal and Installation

INFOID:0000000005234701

REMOVAL

- 1. Remove the inside mirror cover.
- 2. Remove TORX bolt.
- 3. Disconnect harness connector from inside mirror.
- 4. Slide the inside mirror upward to remove.

INSTALLATION

Install in the reverse order of removal.

OUTSIDE MIRROR DOOR MIRROR ASSEMBLY

DOOR MIRROR ASSEMBLY: Exploded View


INFOID:0000000005234702

Α

В

D

Е



- Door mirror cover
- Door mirror corner cover
- 3. Glass mirror

Door mirror assembly




DOOR MIRROR ASSEMBLY: Removal and Installation

INFOID:0000000005234703

REMOVAL

- 1. Remove door finisher.
 - Coupe models: Refer to INT-14, "Removal and Installation".
 - Roadster models: Refer to <u>INT-43, "Removal and Installation"</u>.
- 2. Remove door mirror corner cover (1).
 - Hold lower portion of door mirror corner cover by a hand, and then disconnect 2 pawls.
 - Remove door weather-strip (2) from door mirror corner cover
 - Pull door mirror corner cover toward vehicle rear, and then remove.



Disconnect door mirror harness connector.

MIR

K

M


Ν

Ρ

OUTSIDE MIRROR

< REMOVAL AND INSTALLATION >

 Remove door weather-strip (2) from door mirror assembly (1) (A) portion.




5. Remove door mirror mounting nuts, and remove door mirror assembly.

INSTALLATION

Install in the reverse order of removal.

GLASS MIRROR

GLASS MIRROR: Exploded View



- 1. Door mirror cover
- 2. Door mirror corner cover
- 3. Glass mirror

Door mirror assembly

^ : Pawl

GLASS MIRROR: Disassembly and Assembly

INFOID:0000000005234705

INFOID:0000000005234704


DISASSEMBLY

- 1. Place the glass mirror upward.
- 2. Put a strip of protective tape (B) on housing assembly.
- As shown in the figure, insert a small flat-bladed screwdriver (A) between glass mirror (1) and actuator (2).
 Push up both pawls simultaneously to remove glass mirror lower half side.
 NOTE:

OUTSIDE MIRROR

< REMOVAL AND INSTALLATION >

Insert flat-bladed screwdriver into recesses (3), and push up while rotating (twisting) to make work easier.



- 4. Remove two terminals of mirror heater attachment.
- 5. Lightly lift up lower side of glass mirror, and detach both pawls of upper side as if pulling it out to disassemble glass mirror from actuator.

NOTE:

Be careful not to allow grease on sealing agent in center of mirror or back side of glass mirror.

ASSEMBLY

Assemble in the reverse order of disassembly.


CAUTION:

After installation, visually check that pawls are securely engaged.

DOOR MIRROR COVER

DOOR MIRROR COVER: Exploded View

INFOID:0000000005234706



- 1. Door mirror cover
- Door mirror assembly
- Door mirror corner cover
- Glass mirror

______: Pawl

DOOR MIRROR COVER: Disassembly and Assembly

DISASSEMBLY

Remove the glass mirror. Refer to MIR-22, "GLASS MIRROR: Disassembly and Assembly".

Revision: 2009 July MIR-23 2010 370Z

В

Α

С

D

Е

F

G

Н

J

K

MIR

M

. .

Ν


INFOID:0000000005234707

P

OUTSIDE MIRROR

< REMOVAL AND INSTALLATION >

2. Remove the pawls, and disassemble the door mirror cover from the mirror assembly.



ASSEMBLY

Assemble in the reverse order of disassembly.

CAUTION:

After installation, visually check that pawls are securely engaged.

DOOR MIRROR REMOTE CONTROL SWITCH

< REMOVAL AND INSTALLATION >

DOOR MIRROR REMOTE CONTROL SWITCH

Exploded View

INFOID:0000000005234708

Α

В

D

Е

F

Н

Refer to INT-14, "Exploded View"

INFOID:0000000005234709


Removal and Installation

REMOVAL

- 1. Remove the driver side door finisher.

 - Coupe models: Refer to <u>INT-14, "Removal and Installation"</u>.
 Roadster models: Refer to <u>INT-43, "Removal and Installation"</u>.
- 2. Remove door mirror remote control switch (1) from driver side door finisher (2) using flat-bladed screwdriver (A).





INSTALLATION

Install in the reverse order of removal.

MIR

K

M

Ν

0

Р

MIR-25 Revision: 2009 July 2010 370Z