



SERVICE BULLETIN

Classification: BT08-002	Reference: NTB08-031	Date: March 6, 2008
-----------------------------	-------------------------	------------------------

2008 ROGUE; CREAKING NOISE FROM CONSOLE FINISHER

APPLIED VEHICLE: 2008 Rogue (S35)

IF YOU CONFIRM

There is a creaking noise coming from the console finisher assembly when making turns.

ACTIONS

- Remove the console finisher assembly.
- Put tape from the squeak and rattle kit on the 9 ribs located on the upper half of the console finisher assembly. See Figure 1.

NOTE: Some models only have 7 ribs.



Figure 1

IMPORTANT: The purpose of "ACTIONS" (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire Service Procedure (starting on page 3) as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
Adhesive Tape From Squeak and Rattle Kit	68239-13E00	*As needed

*This product will serve multiple vehicles and is considered a shop supply.

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Repair Console Finisher per TSB	(1)	VX98AA	ZL	41	0.4 hrs

(1) Use P/N 96941-JM00A as the PFP.

SERVICE PROCEDURE

1. Remove the console finisher assembly using a trim tool.
 - Refer to section IP in the Electronic Service Manual (ESM) for removal procedure.
2. Cut 9 0.39" – 0.59" long x 0.19" wide (10-15 mm long x 5 mm wide) strips of the squeak and rattle tape.
3. Using a needle nose plier, put tape from the squeak and rattle kit on the outer edge of the 9 ribs located underneath the upper half of the console finisher assembly, as shown in Figure 2.

NOTE: Some models only have 7 ribs.



Figure 2

TP080009

4. Install the console finisher assembly in reverse order of removal.
5. Check to make sure the issue has been resolved.