

7

NISSAN MOTOR CORPORATION IN U.S.A.

15-11-11

Post Office Box 191 Gardena, California 90248-0191 Telephone: (213) 532-3111

SERVICE BULLETIN

Classification: BR92-002	Section: Brake	Models:	All Models w/ ABS	
Reference: TECHNICAL BULLETIN NTB92-044		Date:	June 4, 1992	

A.B.S. 'SELF-CHECK' CLUNK NOISE

APPLIED MODEL: All models equipped with ABS brakes

SERVICE INFORMATION

Some customers may notice a "clunk" noise after each engine start when their vehicles are initially driven in forward or reverse gear. The "clunk" noise may be accompanied by a brief "pulsation" in the brake pedal. This condition is caused by the A.B.S. system performing a self-check function and is normal.

The self-check function only occurs the first time the vehicle reaches 4 mph or greater in forward or reverse gear after starting the engine. This check automatically activates the A.B.S. actuator causing the brake pedal to pulsate momentarily.

NISSAN MOTOR CORPORATION IN U.S.A.

Technical Publications Department

1/1

Index 1 029221