



*for #2
L*

TECHNICAL DATABASE INFORMATION

Record ID: FC0007827	Source Reference Number: FI76175	Classification: OCT '92
Subject: DASH SQUEAK	Entered On: 10/21/92	
Model Line: PTH	Model Year: 91 92 93	

Technical Information Abstract:

INFO SOURCE: AUGIE, WESTBURY NISSAN, LTD., NY.

SYMPTOMS: SQUEAK FROM LEFT SIDE OF DASH. OCCURS AT LOW SPEEDS OF 10-25 MPH.
'92 PTH COULD DUPLICATE INCIDENT BY BOUNCING VEHICLE UP AND DOWN. VERIFIED THAT NOISE IS NOT RELATED TO WINDSHIELD MOULDINGS.

FIELD FIX: FOUND THE LEFT FRONT FENDER WAS RUBBING AGAINST THE COWL AND WINDSHIELD. THE FENDER WAS NOT FULLY TRIMMED OF EXCESS MATERIAL ALONG THE EDGES WHERE THE FENDER, WINDSHIELD AND COWL MEET. BENT THE EDGE OF THE FENDER AWAY FROM COWL AND WINDSHIELD TO RESOLVE.