



JFA

T

SERVICE BULLETIN

Classification: MT93-003	Section: Manual Transmission	Models: 1987-92 Pathfinder
Reference: TECHNICAL BULLETIN NTB93-021	Date: January 26, 1993	

M/T SHIFT LEVER VIBRATION IN 3RD GEAR

APPLIED MODEL: 1987-92 Pathfinder (WD21) built before May 29, 1992

SERVICE INFORMATION

Some customers may complain of a slight shifter vibration when accelerating after coasting in third gear. A countermeasure third gear assembly and needle bearing have been developed for this incident.

If this type of shift lever vibration is reported, replace the third gear assembly and needle bearing with the countermeasure parts listed below.

PARTS INFORMATION

Part Description	New Part	Former Part
3rd gear assy	32261-31G75	32261-31G70
3rd gear needle bearing	32203-C8005	32203-C8001

WARRANTY INFORMATION

Operation	Op Code	PNC	CS	CT	FRT
R&I Manual transmission	HC01AA	32260	4R or 4S	35	*
combination:					
O'haul Manual transmission	HC031A	32260	4R or 4S	35	*

*Please reference "1992-93 Nissan Flat Rate Manual" section 'HC' for appropriate FRT for 'Z', 'KA', or 'VG' engine, 2WD or 4WD

NISSAN MOTOR CORPORATION U.S.A.

Technical Publications Department