



# TECHNICAL DATABASE INFORMATION

Record ID: <b>FC0008541</b>	Source Reference Number: <b>BBS</b>	Classification: <b>JUN '93</b>
Subject: <b>IDLE FLUCTUATES</b>	Entered On: <b>06/03/93</b>	
Model Line: <b>NIS</b>	Model Year: <b>90 91 92 93 94</b>	

## Technical Information Abstract:

INFORMATION: IF YOU HAVE A VEHICLE THAT EXHIBITS AN INCIDENT OF FLUCTUATING  
ALL MODELS IDLE, PLEASE MAKE THE FOLLOWING INITIAL CHECKS:  
& YEARS W/ 1) CHECK/SET BASE IDLE SETTING  
ECCS SYSTEM 2) CHECK/ADJUST TPS SETTING  
3) TPS IDLE VOLTAGE STABILITY SHOULD BE 'ROCK STEADY'--IF NOT,  
CHECK HARNESS SPLICE FOR TPS, AND WATER TEMP SENSOR GROUND.  
4) CHECK THROTTLE CHAMBER/THROTTLE PLATE FOR BINDING OR BEING  
GUMMED UP.

NOTE: PLEASE REFER TO THE EF & EC SECTION FOR BASE IDLE AND TPS SETTING PRO-  
CEDURES AND SPECIFICATIONS IN THE APPROPRIATE SERVICE MANUAL.

.....  
Index # **034853**  
.....