## **Technical Bulletin**



# SERVICE BULLETIN

Classification: Reference: Date:

EL06-008c NTB06-065c September 4, 2007

## POWER WINDOW "AUTO UP" INOPERATIVE

This bulletin amends NTB06-065b. The Applied Vehicles has been expanded. Please discard all previous versions of this bulletin.

APPLIED VEHICLES: 2007 – 2008 Versa (C11)

2007 – 2008 Altima Sedan (L32) 2007 – 2008 Altima Hybrid (HL32)

2008 Altima Coupe (CL32) 2004 – 2008 Armada (TA60) 2005 – 2008 Frontier (D40) 2004 – 2008 Maxima (A34) 2003 – 2007 Murano (Z50) 2005 – 2008 Pathfinder (R51) 2004 – 2008 Quest (V42) 2007 – 2008 Sentra (B16) 2004 – 2008 Titan (A60) 2005 – 2008 Xterra (N50) 2003 – 2008 350Z (Z33)

2008 Rogue (\$35)

### IF YOU CONFIRM

A power window "Auto Up" will not work.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

#### **ACTION**

Perform the following initialization procedure:

- 1. Turn the ignition switch ON.
- 2. Open the window—all the way DOWN.
- 3. Pull all the way UP on the switch and hold (close the window).
  - Continue holding the switch <u>all the way UP for 4 seconds</u> after the window is closed.
- 4. Confirm the window is now operating correctly.

### NOTE:

- If the window is still not operating correctly, refer to ASIST and the Service Manual for further diagnosis and repair information.
- The above initialization procedure must be performed if any of the following occur:
  - Battery cable is disconnected
  - > Power window switch connector is disconnected
  - Power window regulator is replaced
  - Power window motor is replaced
  - Window glass is removed
  - Window glass run rubber is replaced
  - Power window fuse is blown
  - Window is partly opened and/or closed many times without being fully closed.